



Phoz-Brite

Multi-Purpose Acid Cleaner

Multiuso Limpiador Ácido

- Concentrated • Non-Fuming • Powerful
- Versatile • Cleans • Restores • Brightens



Technical Data Sheet

PRODUCT DESCRIPTION:

A versatile, non-fuming formulation that combines the power of phosphoric acid with surfactants and water-based solvents.

USES:

Designed for removing dull soap film, rust, lime and scale from various surfaces. Also cleans and brightens aluminum, stainless steel, copper and chrome. It can also be used to prepare steel or aluminum for painting.

ADVANTAGES:

Removes rust, lime and scale as well as cleaning and brightening various types of tile, stone, aluminum and other soft metals. Non-fuming.

SPECIFICATIONS:

- Active Ingredients: 54%
- pH: 1-2
- Color: Blue
- Solubility in Water: Complete
- Odor: Cherry
- Flash Point: None
- Viscosity: Water Thin
- Weight per Gallon: 9.6 Lbs.



Recyclable packaging

PRODUCT/CONTAINER DISPOSAL:

Dispose of used/unwanted product according to state and local regulations. Offer container for recycling.

SIZES AVAILABLE:

- 1 Gallon Bottle, 5 Gallon Pail, 30 & 55 Gallon Drums.

PRODUCT USE

PRODUCT USE	DILUTION RATE
Delime Automatic Dishwashers	2 oz. per gallon of water
General Cleaning: Shower Stalls, Walls, Floors, Fixtures, Drinking Fountains, Ceramic Tile	4 oz. per gallon of water
Clean/Brighten Stainless Steel, Aluminum, Copper, Chrome	8 oz. per gallon of water
Remove Rust, Oxidation, Heavy Carbonate Copper, Chrome	16 oz. per gallon of water

DILUTION MAY VARY DEPENDING UPON SEVERITY OF SOIL BUILD-UP

DIRECTIONS FOR PRODUCT USE:

ALWAYS PRE-TEST PRODUCT IN AN INCONSPICUOUS PLACE DELIMING:

1. Add concentrate per chart above to wash or rinse tank.
2. Run machine for 15 minutes.
3. Allow to drain and follow with dishwashing detergent.

GENERAL CLEANING:

1. Apply diluted solution to surface using a sponge, mop or trigger sprayer.
2. Rinse surface with clear water and wipe dry.

BRIGHTEN METAL SURFACES:

1. Apply diluted solution to surface using a sponge, mop or trigger sprayer.
2. Rinse surface with clear water and wipe dry.

RUST REMOVAL:

1. Add concentrate per chart above to wash or rinse tank.
2. Allow to soak for 10 minutes.
3. Rinse well with clean water.



It is recommended that protective gloves and safety glasses be worn when using this and all cleaning products.

Refer to SDS for further safety information.



MANUFACTURED BY:



AMERICAN Cleaning Solutions
Division of American Wax Company, Inc.

39-30 Review Avenue
Long Island City, New York 11101
1-888 WAX PLUS • (718) 392-8080 Fax: (718) 482-9366
Visit us on the web! www.cleaning-solutions.com

