



# Jackhammer

## Mop-A-Way Stripper & Emulsifier

Estripádo Emulsionante

- Water-Based • Penetrates
- Solubilizes Finish Quickly



### Technical Data Sheet

#### PRODUCT DESCRIPTION:

A formulation of water-based solvents, amine compounds and wetting agents which rapidly dissolve multiple layers of finish and sealer with or without a floor machine.

#### USES:

Easy & fast removal of multiple coats of floor finish or wax without the use of a conventional floor machine and stripping pad.

#### ADVANTAGES:

Cuts through many layers of finish or wax in minutes. Just mop on, let sit for only minutes, mop agitate and then pick up by mop or wet vacuum before rinsing. A scrubbing machine is not normally necessary depending on severity of build-up.

#### SPECIFICATIONS:

Active Ingredients: 40%  
 pH: 12.5  
 Color: Blue  
 Solubility in Water: Complete  
 Odor: Butyl  
 Flash Point: None  
 Viscosity: Water Thin  
 Weight per Gallon: 8.78 Lbs.

#### PRODUCT/CONTAINER

#### DISPOSAL:

Dispose of used/unwanted product according to state and local regulations. Offer container for recycling.

#### SIZES AVAILABLE:

1 Gallon Bottle, 5 Gallon Pail, 30 & 55 Gallon Drums.



Recyclable packaging

#### PRODUCT USE

#### DILUTION RATE

Light Build-Up	8 oz. per gallon of warm water
Moderate Build-Up	16 oz. per gallon of warm water
Heavy Build-Up	Equal parts concentrate & water

DILUTION MAY VARY BASED ON BUILD-UP OF OLD FINISH ON FLOOR SURFACE  
PRODUCT DESIGNED FOR USE WITH WARM WATER

#### DIRECTIONS FOR PRODUCT USE:

FOR BEST RESULTS, USE OF FLOOR MACHINE RECOMMENDED

1. Dilute concentrate per the chart above based on the amount of build-up.
2. Apply to a small test area to determine the amount of time needed to adequately strip floor.
3. Mop diluted solution liberally onto floor surface working in 5' x 5' sections.
4. Allow to stand 4-5 minutes. Keep area wet.
5. If surface is unusually dirty or scuffed, use mop, brush or floor machine to agitate and loosen dirt and finish; for stubborn marks scrub using a stripping pad.
6. Pick up solution with a mop or wet-vac machine. Rinse with clear water.
7. Allow floor to dry.
8. Apply first coat of finish or floor sealer in full uniform coat. Apply additional coats of floor finish as required.

**CAUTION:** Never allow solution to dry on floor. Always test solution on an inconspicuous area of floor to be stripped to check compatibility. Emulsified floor finish and wax are very slippery; keep area clear until surface is completely dry.



It is recommended that protective gloves and safety glasses be worn when using this and all cleaning products. Refer to SDS for further safety information.



#### MANUFACTURED BY:



**AMERICAN** Cleaning Solutions  
 Division of American Wax Company, Inc.

39-30 Review Avenue  
 Long Island City, New York 11101  
 1-888 WAX PLUS • (718) 392-8080 Fax: (718) 482-9366  
 Visit us on the web! [www.cleaning-solutions.com](http://www.cleaning-solutions.com)

