



Mop & Strip Stripper/Emulsifier

Estripádo/Emulsionante

- Economical • Fast Acting
- Emulsifies Old Finish For Easy Removal



Technical Data Sheet

PRODUCT DESCRIPTION:

A formulation of water-based solvents, amine compounds and wetting agents which rapidly penetrate and dissolve multiple layers of finish and sealer with or without a floor machine.

USES:

Strips off multiple coats of wax & finish without the use of a floor machine and stripping pad.

ADVANTAGES:

Reliquifies all types of floor finishes quickly. Removes build-up without the use of a floor machine. Cuts thru multiple coats of finish in one application to save time and labor. A very powerful & efficient stripper. A mop is used to break the bond of the floor finish.

SPECIFICATIONS:

Active Ingredients: 25%
 pH: 12.5-13
 Color: Purple
 Solubility in Water: Complete
 Odor: Butyl
 Flash Point: None
 Viscosity: Water Thin
 Weight per Gallon: 8.4 Lbs.

PRODUCT/CONTAINER

DISPOSAL:

Dispose of used/unwanted product according to state and local regulations. Offer container for recycling.

SIZES AVAILABLE:

1 Gallon Bottle, 5 Gallon Pail, 30 & 55 Gallon Drums.



Recyclable packaging

PRODUCT USE

DILUTION RATE

Light Build-Up	8 oz. per gallon of warm water
Medium Build-Up	32 oz. per gallon of warm water
Heavy Build-Up	64 oz. per gallon of warm water

DILUTION MAY VARY BASED ON BUILD-UP OF OLD FINISH ON FLOOR SURFACE
PRODUCT DESIGNED FOR USE WITH WARM WATER

DIRECTIONS FOR PRODUCT USE:

FOR BEST RESULTS, USE OF FLOOR MACHINE RECOMMENDED

1. Dilute concentrate per the chart above based on the amount of build-up.
2. Apply to a small test area to determine the amount of time needed to adequately strip floor.
3. Mop diluted solution liberally onto floor surface working in 5' x 5' sections.
4. Allow to stand 4-5 minutes. Keep area wet.
5. If surface is unusually dirty or scuffed, use mop, brush or floor machine to agitate and loosen dirt and finish; for stubborn marks scrub using a stripping pad.
6. Pick up solution with a mop or wet-vac machine. Rinse with clear water.
7. Allow floor to dry.
8. Apply first coat of finish or floor sealer in full uniform coat. Apply additional coats of floor finish as required.

CAUTION: Never allow solution to dry on floor. Always test solution on an inconspicuous area of floor to be stripped to check compatibility. Emulsified floor finish and wax are very slippery; keep area clear until surface is completely dry.



It is recommended that protective gloves and safety glasses be worn when using this and all cleaning products. Refer to SDS for further safety information.



MANUFACTURED BY:



AMERICAN Cleaning Solutions
 Division of American Wax Company, Inc.

39-30 Review Avenue
 Long Island City, New York 11101
 1-888 WAX PLUS • (718) 392-8080 Fax: (718) 482-9366
 Visit us on the web! www.cleaning-solutions.com

